


***SEWING CHEST DOUBLE***  
***ШВЕЙНЫЙ СУНДУК DOUBLE***



# ***SYMBOLS***



***ATTENTION***

***ВНИМАНИЕ***




***ASSEMBLY & ADJUSTMENT***

***СБОРКА РЕГУЛИРОВКА***




***OPERATION***

***ЭКСПЛУАТАЦИЯ***



***INDICATING MARK***

***ОБОЗНАЧЕНИЕ***

















***EVEN SURFACE***


***РОВНАЯ ПОВЕРХНОСТЬ***

010001 1x 010002 1x 010003 1x 010004 1x 010006 1x  
 010022 1x 010026 1x 010032 1x 010033 1x 010044 1x


<p>1x 020013 CR</p> 	<p>1x 020013 CL</p> 	
<p>1x 020015 DR</p> 	<p>1x 020015 DL</p> 	
<p>2x 020007</p> 	<p>4x 020035</p> 	<p>2x 020037</p> 

<p>030001          3 * 16        4x</p>	<p>030002          3,5 * 16        22x</p>	<p>030003          6,2 * 50        6x</p>	<p>030009          M4 * 20        2x</p>	<p>030011          φ15        6x</p>	<p>030012          φ18        23x</p>
<p>030013          L = 35        23x</p>	<p>030014          φ15 h12        23x</p>	<p>030015          φ8 * 30        27x</p>	<p>030028          3,9 * 16        16x</p>		

<p>1x 050004</p> 	<p>1x 050005</p> 
<p>2x 050006</p> 	<p>1x S4</p> 





S 4






4




\*  
Входит в комплект стола.  
Included into table set.







010032



010044

